



Runway Grooving, Norman Wells, NWT





Presentation Outline

- Project timeline
- User concerns
- Problem
- Options
- Grooving
- Results and recommendations



Timeline

1. Paved in 2006
 - High fines content in aggregate
 - High asphalt content -> smooth surface
 - Paver left ruts along wheel paths
2. May 05, 2007 - B737 hydroplaned
3. Summer 2007 - paving contractor patched ruts
4. April 22, 2010 - B737 hydroplaned
5. July 2010 – conducted runway friction and texture testing
6. Researched remediation options
7. July 06, 2011 - B737 hydroplaned
8. July 14, 2011 - B737 hydroplaned
9. July 26, 2011 started cutting grooves



User Concerns



**Hydroplaning/
Wet Friction**



Incident One

5 May 2007

A B737-200 hydroplaned landing on Runway 27.

- METAR CYVQ 051700Z 15002KT 2 1/2SM -SN OVC020 M00/M03
- The runway was wet with a trace of slush
- One thrust reverser did not deploy
- The aircraft stopped with around 30 m to spare.



Summer 2007 - Ruts



Summer 2007 - Patches



Incident Two

22 April 2010

A B737-200 landing on Runway 27 complained of poor braking.

- METAR CYVQ 221700Z 00000KT 15SM -DZ OVC025 04/02
- Pilot reported poor braking in patched area
- Runway was bare and wet
- Flight was heavier than usual.



Problem Assessment

- Friction survey
- Texture survey
- Cross-slope survey



Friction Survey



Testing Apparatus



Friction Survey




GripTester



Friction Survey Results

Norman Wells Airport
Runway 09-27, July 5-6 2010
[3m L & R of CL, 0.25mm water]




Transport Canada Maintenance Planning Runway Average Level = 60
Transport Canada Minimum 100m Maintenance Planning Level = 40
Transport Canada Minimum 100m Action Level = 30



Friction Survey Results

Norman Wells Airport
Runway 09-27, July 5-6 2010
 [Multiple Offsets, 0.25mm water]



Transport Canada Maintenance Planning Runway Average Level = 60
 Transport Canada Minimum 100m Maintenance Planning Level = 40
 Transport Canada Minimum 100m Action Level = 30




Texture Survey



**ASTM E2380-05
Outflow Meter**



Texture Survey Results






Cross-Slope Survey



October 2010



Cross-Slope Survey



Threshold Runway 27




Friction Improvement Options

CYVQ IMPROVEMENT OPTIONS: COST COMPARISONS

Treatment	Shotblasting	Standard Grooves	Trapezoidal Grooves	Diamond Grinding
cost estimate	\$242,099	\$181,357	\$205,624	\$437,224
recurrence	3	15	15	5
cost/year	\$80,700	\$12,090	\$13,708	\$87,445



Groove Profile




TYPICAL GROOVE DETAIL

NOTE: GROOVES SHALL BE PERPENDICULAR TO R/W CENTERLINE.
(BASIC BID)



Test Grooves



October 2010



Test Grooves



January 2011




Decision

- Tender for grooving closed 25 May 2011
- Contractor was delayed at USA/Canada border
- Results from delay:
 - 6 July 2011: Incident Three: B737-200 hydroplaned landing Runway 27.
 - 13 July 2011: TC issued a Program Validation Inspection requiring a Corrective Action Plan regarding the runway surface.
 - 14 July 2011: Incident Four: B737-200 hydroplaned landing Runway 09.
- 26 July 2011—began work of grooving contract.



Cutting Grooves



July 2011



Cutting Grooves



July 2011



Cutting Grooves



July 2011



Results of Grooving - Summer

- Airlines are pleased. Friction has improved and there have been no more incidents.
- Grooved areas dry quickly after the rain.
- Sweeping during and after rain storms is no longer required.



Results of Grooving - Summer



- 8 May 2012
- Grooved area dry, non-grooved area still wet.



Results of Grooving - Winter

- Friction index was .05-.08 higher where grooved.
- Only used 65 tonnes of sand (typical use is 100 T).
- No chemicals used this winter
- CRFI improved more quickly during sweeping.
- Ice came off the surface more easily.
- Runway dried more quickly after wet snow and slush.
- Favourable feedback from the airlines.



Some Issues

- Damage to runway crown from snow removal.
- Under icy conditions, aircraft had difficulty turning on the threshold areas which were not grooved.
- Snow compacts in grooves but comes out with sweeping.
- This winter season we went through 3 cores of brushes. The normal was 2 cores per year.
- Grooves are gone in some of the runway patch areas.



Damage at Runway Crown





Ungrooved Areas are Slippery



- 5 May 2012
- Ungrooved Threshold 27 is slippery.
- CRFI .35 in this location.
Temperature -4°C




Compact Snow in Grooves



- 5 May 2012
- First sweeper pass
- CRFI .42
Temp. -4°C




Compact Snow in Grooves



- May 05, 2012
- First sweeper pass--detail




Compact Snow in Grooves



- May 05, 2012
- Second sweeper pass
- CRFI .57 -1°C



Compact Snow in Grooves



- 5 May 2012
- Third sweeper pass
- Most of the compact snow is gone



Increased Broom Wear



- Still on the broom
10 May 2012
(using every inch)



Wear at Patch Edges



10 May 2012



Recommendations for Future Grooving

- Could we use grooves to improve winter friction elsewhere?
- Grooving should be done the same or following year of resurfacing of runway.
- Monitor the grooves during warm weather to see if there is any damage done by aircraft turning.



The End—Questions?

