

Airfield Lighting & Operational Continuity

SWIFT
VANCOUVER SEPT 17-19 2024



SWIFT
VANCOUVER SEPT 17-19 2024

MATT FALCIONI

25 years experience in Airport/Airfield Operations

- Manager Operations, Airfield Ground Operations
- Manager, Airfield Maintenance Runways & Taxiways



Balraj Parmar, P .Eng.,FMP

- **Principal, Aviation Electrical Engineer at WSP, based in BC**
- **Worked as Senior Electrical Engineer at Stantec, based in Vancouver, BC**
- **Worked as Senior Electrical Engineer at GTAA**
- **30+ Years of Experience**
 - Airfield lighting electrical design
 - Electrical Maintenance
 - Terminal Infrastructure
 - Construction site supervision
 - Canadian Airports Electrical Association, President

Keeping Surfaces Available Day to Day...

Airfield Maintenance

- Operational Serviceability
- Preventative maintain of the surfaces
- Serviceability Inspection

Airfield Electrical


- Maintains lighting
- Preventative Maintenance on lights
- Maintenance Inspections

Airport Development & Technical Services

- Supports the Operational Teams with Infrastructure Strategies



SOME OF THE CHALLENGES...




Toronto Pearson



SOME OF THE CHALLENGES...



SOME OF THE CHALLENGES...



SOME OF THE CHALLENGES...



SOME OF THE CHALLENGES...



**YYZ July 2024
Monthly Aircraft
Movements
34500**

**A66%
D12%**

**A11%
D19%**

**81% of Departure
23% of Arrivals
15000 total movements**

Aging Infrastructure




Aging Infrastructure



Aging Infrastructure



Aging Infrastructure



Aging Infrastructure



Aging Infrastructure

RWY 05 @ H2

Title

[No Title]

What are we doing...

- **Increase Inspections Frequency**
- **LOWVIS Serviceability Inspection**
- **Cross Departmental Inspections**
- **Increased Access (Smaller Windows)**
- **Right Material for the Job**
- **Coordination between Nav, Carriers and Airport Authority for priority closures**

Identifying Deficiencies





Small pieces of asphalt start missing around can. This will create bigger issues if not addressed early.



This was likely caused by improper compaction around the inset light when it was initially installed.

**Most likely didn't
have a solid
concrete base
underneath or a
shallow inset can
was installed**

**Inset can Sunken
into asphalt**



Concrete/Grout around inset can started breaking up

- Can Generate FOD
- Asphalt -> Concrete isn't ideal
or a good match



Mastic (Hot Applied)

Colas and Sand

Delpatch

Two-Part Epoxy Tubes

Material Options For Repairs



Two-Part Epoxy Tubes

Material Options For Repairs

Mastic (Hot Applied)

Colas and Sand

Delpatch



SWIFT

Delpatch

Material Options For Repairs

Two-Part Epoxy Tubes

Mastic (Hot Applied)

Colas and Sand



Colas and Sand

Material Options For Repairs

Delpatch Elastomeric Concrete can accept traffic in as little as one hour after the final pour when installed in normal working temperatures


Delpatch

Two-Part Epoxy Tubes

Mastic (Hot Applied)




Matic Repair



Delpatch Repair




As-Builts/Base Plan Drawings




01 TYPICAL INSTALLATION OF NEW INSET LIGHT FIXTURE IN NEW HMAC
 SCALE: 1:10

As-Builts/Base Plan Drawings, cont'd



As-Builts/Base Plan Drawings, cont'd



ISOMETRIC VIEW

NOTES:

- MAINTAIN 75mm MIN. COVER ON REBAR.




TYPICAL DETAIL FOR REBAR CAGE

SCALE: NTS





wsp





N 43° 40' 37", W 79° 39' 48"
N Service Rd
Mississauga ON
Canada

Toronto Lester B. Pearson International Airport



**YVR SOUTH AIRFIELD
PAVEMENT
REHABILITATION**
****2023 (TAXIWAY L, L2,
L4, D3) ****






As-Builts/Base Plan Drawings, cont'd

- **As-Built Drawing Update**
 - Maintain a central database of base cans, extension rings and spacers etc..
 - Get a good experienced design consultant & contractor for the project
 - Pre-design survey of the site to find issues with inset light/cans.

What next?

- Emergency Temporary Lighting
- Proof of Concept – AI Feasibility
- Full Infrastructure Upgrade





QUESTIONS?